

<b>AVIATION BRAKE SERVICE</b>				
<b>CAPABILITY LIST</b>				
<b>JDC</b>	<b>11/23/21</b>			
<b>MAKER</b>	<b>DESCRIPTION</b>	<b>P/N</b>	<b>MANUAL</b>	<b>M.F.G. CODE</b>
<b>MABS</b>	<b>BRAKE</b>		<b>32-43-24</b>	<b>AP-422</b>
<b>MABS</b>	<b>MLGW</b>	<b>5003384</b>	<b>32-40-45</b>	<b>AP-466</b>
<b>MABS</b>	<b>NLGW</b>	<b>5003706</b>	<b>32-46-15</b>	<b>AP-503</b>
<b>MABS</b>	<b>MLGW</b>	<b>5004069</b>	<b>32-40-56</b>	<b>AP-504</b>
<b>MABS</b>	<b>NLGW</b>	<b>5006227</b>	<b>32-46-19</b>	<b>AP-604</b>
<b>MABS</b>	<b>NLGW</b>	<b>5006528 / 5006528-1</b>	<b>32-46-18</b>	<b>AP-588</b>
<b>MABS</b>	<b>MLGW</b>	<b>5006566</b>	<b>32-40-71</b>	<b>AP-607</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5006575</b>	<b>32-43-63</b>	<b>AP-608</b>
<b>MABS</b>	<b>NLGW</b>	<b>5006673</b>	<b>32-46-20</b>	<b>AP-609</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5007555</b>	<b>32-43-72</b>	<b>AP-639</b>
<b>MABS</b>	<b>NLGW</b>	<b>5007998</b>	<b>32-46-24</b>	<b>AP-646</b>
<b>MABS</b>	<b>MLGW</b>	<b>5008131-5</b>	<b>32-40-81</b>	<b>AP-651</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5009027</b>	<b>32-43-86</b>	<b>AP-690</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5009027-5</b>	<b>32-44-74</b>	<b>AP-789</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5010614</b>	<b>32-43-99</b>	<b>AP-723</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5010933-1/-2</b>	<b>32-43-93</b>	<b>AP-677</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5010520-1</b>	<b>32-43-96</b>	<b>AP-716</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5010933-SERIES</b>	<b>32-44-75</b>	<b>AP-791</b>
<b>MABS</b>	<b>MLGW</b>	<b>5010571/-1/-2</b>	<b>32-40-98</b>	<b>AP-715</b>
<b>MABS</b>	<b>MLGW</b>	<b>5011166</b>	<b>32-41-20</b>	<b>AP-731</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5011809-SERIES</b>	<b>32-44-65</b>	<b>AP-747</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5012609</b>	<b>32-43-14</b>	<b>AP-766</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5012889</b>	<b>32-44-72</b>	<b>AP-785</b>
<b>MABS</b>	<b>NLGW</b>	<b>5013640</b>	<b>32-46-30</b>	<b>AP-795</b>
<b>MABS</b>	<b>MLGW</b>	<b>5013641</b>	<b>32-42-14</b>	<b>AP-794</b>

<b>MABS</b>	<b>BRAKE</b>	<b>5013642</b>	<b>32-44-77</b>	<b>AP-793</b>
<b>MABS</b>	<b>NLGW</b>	<b>9532186-2/-3</b>	<b>32-46-09</b>	<b>AP-417</b>
<b>MABS</b>	<b>NLGW</b>	<b>9531502</b>	<b>32-46-06</b>	<b>AP-143</b>
<b>MABS</b>	<b>MLGW</b>	<b>9540512 / -1</b>	<b>32-02-00</b>	<b>AP-695</b>
<b>MABS</b>	<b>MLGW</b>	<b>9541587</b>	<b>32-40-01</b>	<b>AP-273</b>
<b>MABS</b>	<b>NLGW</b>	<b>9541874</b>	<b>32-46-16</b>	<b>AP-507</b>
<b>MABS</b>	<b>NLGW</b>	<b>9543367</b>	<b>32-40-01</b>	<b>AP-255</b>
<b>MABS</b>	<b>NLGW</b>	<b>9543426</b>	<b>32-46-11</b>	<b>AP-471</b>
<b>MABS</b>	<b>MLGW</b>	<b>9543809</b>	<b>32-40-05</b>	<b>AP-529</b>
<b>MABS</b>	<b>MLGW</b>	<b>9544382</b>	<b>32-40-24</b>	<b>AP-309</b>
<b>MABS</b>	<b>MLGW</b>	<b>9544455</b>	<b>32-40-27</b>	<b>AP-427</b>
<b>MABS</b>	<b>NLGW</b>	<b>9550107</b>	<b>32-40-01</b>	<b>AP-332</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9550266/661/1062</b>	<b>32-40-30</b>	<b>AP-330</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9550273</b>	<b>32-40-03</b>	<b>AP-738</b>
<b>MABS</b>	<b>NLGW</b>	<b>9550328</b>	<b>32-40-01</b>	<b>AP-269</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9550338</b>	<b>32-43-39</b>	<b>AP-473</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9550402 .</b>	<b>T.04B 1-2-133</b>	<b>OB9R2</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9550504</b>	<b>32-40-07</b>	<b>AP-531</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9560569</b>	<b>32-40-02</b>	<b>AP-300</b>
<b>Page 1 of 10</b>				
<b>AVIATION BRAKE SERVICE</b>				
<b>MANUAL CONTROL</b>				
<b>MAKER</b>	<b>DESCRIPTION</b>	<b>P/N</b>	<b>MANUAL</b>	<b>M.F. CODE</b>
<b>MASS</b>	<b>MLGW</b>	<b>9560645</b>	<b>32-40-21</b>	<b>AP-247</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9560746</b>	<b>32-40-01</b>	<b>AP-234</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9560788</b>	<b>32-40-33</b>	<b>AP-263</b>

<b>MABS</b>	<b>BRAKE</b>	<b>9560861</b>	<b>32-40-34</b>	<b>AP-298</b>
<b>MABS</b>	<b>MLGW</b>	<b>9560892</b>	<b>32-40-22</b>	<b>AP-260</b>
<b>MABS</b>	<b>BRAKE</b>	<b>90002340</b>	<b>32-49-30</b>	<b>AP-873</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5000268-5</b>	<b>32-43-03</b>	<b>AP-541</b>
<b>MABS</b>	<b>MLGW</b>	<b>5000306-X</b>	<b>32-41-01</b>	<b>AP-380</b>
<b>MABS</b>	<b>BRAKE</b>	<b>50004321-X</b>	<b>32-43-50</b>	<b>AP-509</b>
<b>MABS</b>	<b>MLGW</b>	<b>5004899-X</b>	<b>32-40-63</b>	<b>AP-515</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5000709-X</b>	<b>32-43-01</b>	<b>AP-388</b>
<b>MABS</b>	<b>MLGW</b>	<b>5000757-X</b>	<b>32-41-02</b>	<b>AP-390</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5000758-10R</b>	<b>32-43-02</b>	<b>AP-391</b>
<b>MABS</b>	<b>NLGW</b>	<b>50008133-1</b>	<b>32-46-25</b>	<b>AP-653</b>
<b>MABS</b>	<b>NLGW</b>	<b>5000919-X</b>	<b>32-42-02</b>	<b>AP-392</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5001445-X/5001446-X</b>	<b>32-43-19</b>	<b>AP-415</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5001571-X</b>	<b>32-43-12</b>	<b>AP-560</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5001897-X</b>	<b>32-43-24</b>	<b>AP-422</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5002256(101-8002-3)</b>	<b>32-44-09</b>	<b>Q73-04(98-36</b>
<b>MABS</b>	<b>MLGW</b>	<b>5002460-X</b>	<b>32-40-47</b>	<b>073-5</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5002805-3</b>	<b>32-43-30</b>	<b>AP-447</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5003096-7</b>	<b>32-43-32</b>	<b>AP-455</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5003096-6</b>	<b>32-43-32</b>	<b>AP-455</b>
<b>MABS</b>	<b>MLGW</b>	<b>5003279-X</b>	<b>32-40-46</b>	<b>AP-469</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5003280-X</b>	<b>32-43-37</b>	<b>AP-470</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5003890/-1</b>	<b>Q77-06</b>	<b>Q77-06</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5004070</b>	<b>32-43-49</b>	<b>A P-505</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5004190-6</b>	<b>32-43-74</b>	<b>AP-643</b>
<b>MABS</b>	<b>MLGW</b>	<b>5004320-X</b>	<b>32-40-60</b>	<b>AP-508</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5004321-14</b>	<b>32-43-50</b>	<b>AP-509</b>
<b>MABS</b>	<b>MLGW</b>	<b>5004899-X</b>	<b>32-40-63</b>	<b>AP-515</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5004902-X</b>	<b>32-43-53</b>	<b>AP-516</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5005494-X</b>	<b>32-43-55</b>	<b>AP-527</b>
<b>MABS</b>	<b>MLGW</b>	<b>5005495-X</b>	<b>32-40-65</b>	<b>AP-526</b>

<b>MABS</b>	<b>MLGW</b>	<b>5006028-X</b>	<b>082-01</b>	<b>N/A</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5006249-X</b>	<b>32-43-60</b>	<b>AP-583</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5006575-X</b>	<b>32-43-63</b>	<b>AP-608</b>
<b>MABS</b>	<b>MLGW</b>	<b>5006586-X</b>	<b>32-40-90</b>	<b>AP-678</b>
<b>MABS/BEECH</b>	<b>BRAKE</b>	<b>5006749-5-5R</b>	<b>32-44-66</b>	<b>AP-749</b>
<b>MABS</b>	<b>NLGW</b>	<b>5006450-3</b>	<b>32-46-12</b>	<b>AP-584</b>
<b>MABS/BEECH</b>	<b>MLGW</b>	<b>5006028-4/-5</b>	<b>082-01</b>	<b>Q82-01</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5006749-2/-3/-4/114-800X-X</b>	<b>082-02</b>	<b>082-02</b>
<b>MABS</b>	<b>MLGW</b>	<b>5006856-X</b>	<b>32-40-74</b>	<b>AP-615</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5006857-X</b>	<b>32-43-67</b>	<b>A P-616</b>
<b>Page 2 of 10</b>				
<b>AVIATION BRAKE SERVICE</b>				
<b>MANUAL CONTROL</b>				
<b>MAKER</b>	<b>DESCRIP</b>	<b>P/N</b>	<b>MANUAL</b>	<b>MFG CODE</b>
<b>MABS</b>	<b>NLGW</b>	<b>5006858-X</b>	<b>32-46-21</b>	<b>AP-617</b>
<b>MABS</b>	<b>MLGW</b>	<b>5007376-X</b>	<b>32-40-76</b>	<b>AP-621</b>
<b>MABS</b>	<b>MLGW</b>	<b>5007397-1/-2</b>	<b>32-40-82</b>	<b>AP-660</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5007555-X</b>	<b>32-43-72</b>	<b>AP-639</b>
<b>MABS</b>	<b>MLGW</b>	<b>5007897-X</b>	<b>32-40-79</b>	<b>AP-641</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5007898-X</b>	<b>32-43-73</b>	<b>AF-642</b>
<b>MABS</b>	<b>MLGW</b>	<b>5007995-1</b>	<b>32-40-80</b>	<b>AP-644</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5007996-X</b>	<b>32-43-76</b>	<b>AP-645</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5008132-X</b>	<b>32-43-77</b>	<b>AP-652</b>
<b>MABS</b>	<b>NLGW</b>	<b>5008133;-I</b>	<b>32-46-25</b>	<b>AP-653</b>
<b>MABS</b>	<b>MLGW</b>	<b>5008447-X</b>	<b>32-40-88</b>	<b>AP-671</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5009027-5</b>	<b>32-44-74</b>	<b>AP-789</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5009027-X</b>	<b>32-43-86</b>	<b>AP-690</b>

<b>MABS</b>	<b>MLGW</b>	<b>5009029-X</b>	<b>32-40-94</b>	<b>AP-689</b>
<b>MABS</b>	<b>MLGW</b>	<b>5009963-2</b>	<b>32-40-95</b>	<b>AP-692</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5009850-1</b>	<b>32-43-87</b>	<b>AP-691</b>
<b>MABS</b>	<b>MLGW</b>	<b>5010488-2</b>	<b>32-41-16</b>	<b>AP-724</b>
<b>MABS</b>	<b>NLGW</b>	<b>5010598-SERIES</b>	<b>32-46-27</b>	<b>AP-714</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5010520-SERIES</b>	<b>32-43-96</b>	<b>AP-716</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5010933-SERIES</b>	<b>32-43-93</b>	<b>AP-677</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5011640-SERIES</b>	<b>32-44-63</b>	<b>AP-739</b>
<b>MABS</b>	<b>MLGW</b>	<b>5011740</b>	<b>32-42-11</b>	<b>AP-742</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5011809-3</b>	<b>32-44-65</b>	<b>AP-747</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5012333</b>	<b>32-44-69</b>	<b>AP-768</b>
<b>MABS</b>	<b>MLGW</b>	<b>5012373</b>	<b>32-42-28</b>	<b>AP-767</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5012589-3/-4</b>	<b>32-44-76</b>	<b>AP-792</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5012889; -1/-2</b>	<b>32-44-72</b>	<b>AP-785</b>
<b>MABS</b>	<b>BRAKE</b>	<b>90010199</b>	<b>32-43-02</b>	<b>AP-1114</b>
<b>MABS</b>	<b>MLGW</b>	<b>90010200-1</b>	<b>32-42-34</b>	<b>AP-1113</b>
<b>MABS</b>	<b>BRAKE</b>	<b>90001201</b>	<b>32-45-12</b>	<b>AP-844</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5014198</b>	<b>32-44-25</b>	<b>AP-845</b>
<b>MABS</b>	<b>NLGW</b>	<b>90000581-SERIES</b>	<b>32-49-19</b>	<b>AP-838</b>
<b>MABS</b>	<b>MLGW</b>	<b>90000582</b>	<b>32-49-21</b>	<b>AP-839</b>
<b>MABS</b>	<b>BRAKE</b>	<b>90000583-5/5PR/6/6PR</b>	<b>32-49-23</b>	<b>AP-840</b>
<b>MABS</b>	<b>VALVE</b>	<b>90001196</b>	<b>32-49-25</b>	<b>AP-841</b>
<b>MABS</b>	<b>NLGW</b>	<b>90002021,-1 (2610485-1)</b>	<b>32-46-37</b>	<b>AP-859</b>
<b>MABS</b>	<b>MLGW</b>	<b>90002024,-1 (2610701-2)</b>	<b>32-41-34</b>	<b>AP-857</b>
<b>MABS</b>	<b>BRAKE</b>	<b>90002030/-1 (2610702-3)</b>	<b>32-44-26</b>	<b>AP-858</b>
<b>MABS</b>	<b>MLGW</b>	<b>90002317-SERIES</b>	<b>32-49-28</b>	<b>AP-872</b>
<b>MABS</b>	<b>BRAKE</b>	<b>90002340-SERIES</b>	<b>32-49-30</b>	<b>AP-873</b>
<b>MABS</b>	<b>BRAKE</b>	<b>90005025,-1,-2,-3</b>	<b>32-44-90</b>	<b>AP-912</b>
<b>MABS</b>	<b>MLGW</b>	<b>9540512 /-1</b>	<b>32-02-00</b>	<b>AP-695</b>
<b>MABS</b>	<b>MLGW</b>	<b>9540977-X</b>	<b>32-40-1</b>	<b>AP-696</b>
<b>MABS</b>	<b>NLGW</b>	<b>9543476-X</b>	<b>32-46-07</b>	<b>AP-318</b>

<b>MABS</b>	<b>NLGW</b>	<b>9543705-X</b>	<b>32-46-08</b>	<b>AP-421</b>
<b>MABS</b>	<b>MLGW</b>	<b>9543809, -X</b>	<b>32-40-05</b>	<b>AP-529</b>
<b>MABS</b>	<b>MLGW</b>	<b>9543991, -X</b>	<b>32-40-35</b>	<b>AP-480</b>
	<b>NLGW</b>	<b>9544207-X</b>	<b>32-46-14</b>	<b>AP-494</b>
<b>Page 3 of 10</b>				
<b>AVIATION BRAKE SERVICE</b>				
<b>MANUAL CONTROL</b>				
<b>MAKER</b>	<b>DESCRIP</b>	<b>P/N</b>	<b>MANUAL</b>	<b>MEG CODE</b>
<b>MABS</b>	<b>MLGW</b>	<b>9544382-X</b>	<b>32-40-24</b>	<b>AP-309</b>
<b>MABS</b>	<b>MLGW</b>	<b>9550207-2</b>	<b>32-40-26</b>	<b>AP-62</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9550266; 9550661; 9561062</b>	<b>32-40-30</b>	<b>AP-330</b>
<b>MABS</b>	<b>NLGW</b>	<b>9550267-X</b>	<b>32-46-13</b>	<b>AP-483</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9550338, -X</b>	<b>32-43-39</b>	<b>AP-473</b>
<b>MABS</b>	<b>MLGW</b>	<b>9550463-2</b>	<b>32-40-25</b>	<b>AP-61</b>
<b>MABS</b>	<b>MLGW</b>	<b>9550616 / 9550616-1 / A955061</b>	<b>32-40-02</b>	<b>AP-324</b>
<b>MABS</b>	<b>MLGW</b>	<b>9560571B</b>	<b>32-40-01</b>	<b>AP-299</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9560685-1</b>	<b>32-40-01</b>	<b>AP-231</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9560685</b>	<b>T.O.4B1-1003</b>	<b>OB9R9</b>
<b>MABS</b>	<b>BRAKE</b>	<b>9560743-1</b>	<b>32-40-31</b>	<b>AP-252</b>
<b>MABS</b>	<b>BRAKE</b>	<b>B9560743</b>	<b>32-40-31</b>	<b>AP-252</b>
<b>MABS</b>	<b>MLGW</b>	<b>9560859-X</b>	<b>32-40-20</b>	<b>AP-297</b>
<b>GOODYEAR</b>	<b>MLGW</b>	<b>9550064</b>	<b>03-25BC-1/-2</b>	<b>N/A</b>
<b>MABS</b>	<b>MLGW</b>	<b>9561061</b>	<b>32-40-10</b>	<b>AP-401</b>
<b>MABS</b>	<b>MLGW</b>	<b>A-9550616</b>	<b>32-40-02</b>	<b>AP-324</b>
<b>MABS</b>	<b>MLGW</b>	<b>A9560645</b>	<b>32-40-21</b>	<b>AP-247</b>
<b>MABS</b>	<b>NDT</b>	<b>EDDY CURRENT</b>	<b>32-42-05</b>	<b>AP-763</b>
<b>MABS</b>	<b>NDT</b>	<b>GENERAL</b>	<b>32-42-03</b>	<b>AP-763</b>

<b>MABS</b>	<b>NDT</b>	<b>MAGNETIC</b>	<b>32-42-06</b>	<b>AP-763</b>
<b>MABS</b>	<b>NDT</b>	<b>PENETRANT</b>	<b>32-42-07</b>	<b>AP-763</b>
<b>MABS</b>	<b>NDT</b>	<b>ULTRASONIC</b>	<b>32-42-04</b>	<b>AP-763</b>
<b>MABS</b>	<b>MLGW</b>	<b>5006028-X</b>	<b>082-01</b>	<b>AP-Q842</b>
<b>FORCE</b>	<b>BRAKE</b>	<b>9560685-1</b>	<b>32-40-01</b>	<b>AP-231</b>
<b>JAY-EM</b>	<b>MLGW</b>	<b>250A200</b>	<b>T.O.4W1-4-1013</b>	
<b>JAY-EM</b>	<b>MLGW</b>	<b>8340922-10;-30;-50;-70</b>	<b>T.O.4W1-4-1013</b>	
<b>JAY-EM</b>	<b>O/B WHEEL</b>	<b>250A202</b>	<b>T.O.4W1-4-1013</b>	
<b>JAY-EM</b>	<b>O/B WHEEL-SUB AS</b>	<b>250A325</b>	<b>T.O.4W1-4-1013</b>	
<b>JAY-EM</b>	<b>I/B WHEEL</b>	<b>250A201</b>	<b>T.O.4W1-4-1013</b>	
<b>JAY-EM</b>	<b>I/B WHEEL-SUB AS</b>	<b>250A324</b>	<b>T.O.4W1-4-1013</b>	
<b>JAY-EM</b>	<b>I/B WHEEL-SUB AS</b>	<b>9544009</b>	<b>32-40-02</b>	
<b>JAY-EM</b>	<b>I/B WHEEL-SUB AS</b>	<b>5003245</b>	<b>32-40-02</b>	
<b>MABS</b>	<b>BRAKE</b>	<b>9560685</b>	<b>32-40-01</b>	<b>AP-231</b>
<b>MABS</b>	<b>S.P.M.</b>	<b>STANDARS PRO.</b>	<b>32-46-35</b>	<b>AP-842</b>
<b>MABS</b>	<b>BRAKE</b>	<b>5010933-9/-11</b>	<b>32-44-75</b>	<b>AP-79I</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AH52220</b>	<b>DM1184</b>	<b>AP-2210</b>
<b>MABS</b>	<b>MLGW</b>	<b>AH52689</b>	<b>32-40-2(22)</b>	<b>AP-2042</b>
<b>MABS</b>	<b>MLGW</b>	<b>AH52689</b>	<b>32-40-2(22)</b>	<b>AP-2042</b>
<b>MABS</b>	<b>MLGW</b>	<b>AH53073</b>	<b>32-40-2(22)</b>	<b>AP-2042</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AH52752</b>	<b>32-40-23</b>	<b>AP-2054</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AH52220</b>	<b>DM1184</b>	<b>AP-2209</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AH54450</b>	<b>32-42-89</b>	<b>AP-2104</b>
<b>MABS</b>	<b>NLGW</b>	<b>AH52590, AH52688, AH53374,</b>	<b>32-44-53</b>	<b>AP-2151</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA1292, AHA1802</b>	<b>32-41-71</b>	<b>AP-2073</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1236 / AH53417</b>	<b>32-40-65</b>	<b>AP-2060</b>
<b>MABS</b>	<b>NLGW</b>	<b>AH52997</b>	<b>32-40-62</b>	<b>AP-2057</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA1237 &amp; AHA1501</b>	<b>32-40-91</b>	<b>AP-2063</b>
<b>MABS</b>	<b>NLGW</b>	<b>AHA1290</b>	<b>32-42-55</b>	<b>AP-2087</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1291/AHA1297</b>	<b>32-41-77</b>	<b>AP-2076</b>
<b>MABS</b>	<b>NLGW</b>	<b>AHA1349</b>	<b>32-41-89</b>	<b>AP-2080</b>

<b>MABS</b>	<b>NLGW</b>	<b>AH54452/AH54474</b>	<b>32-42-91</b>	<b>AP-2106</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA1412,1413,1558,1559</b>	<b>32-42-58</b>	<b>AP-2088</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1489/AHA1925</b>	<b>32-42-59</b>	<b>AP-2089</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1648</b>	<b>32-42-82</b>	<b>AP-2098</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA1653</b>	<b>32-42-93</b>	<b>AP-2108</b>
	<b>BRAKE</b>	<b>AHA1693</b>	<b>32-42-84</b>	<b>AP-2100</b>
<b>Page 4 of 10</b>				
<b>AVIATION BRAKE SERVICE</b>				
<b>MANUAL CONTROL</b>				
<b>MAKER</b>	<b>DESCRIPTION</b>	<b>P/N</b>	<b>MANUAL</b>	<b>MEG CODE</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1737</b>	<b>32-42-88</b>	<b>AP-2103</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA1835</b>	<b>32-43-24</b>	<b>AP-2117</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA1884</b>	<b>32-42-98</b>	<b>AP-2112</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1752 / AHA1890 / 9001081</b>	<b>32-42-92</b>	<b>AP-2107</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1837</b>	<b>32-43-25</b>	<b>AP-2118</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA1897</b>	<b>32-43-26</b>	<b>AP-2119</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA1925AHA1489</b>	<b>32-42-59</b>	<b>AP-2089</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA2163</b>	<b>32-44-43</b>	<b>AP-2145</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA2063 { GULFSTREAM P/N 1</b>	<b>32-43-37</b>	<b>AP-2125</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA2070 { GULFSTREAM P/N 1</b>	<b>32-43-38</b>	<b>AP-2126</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA2174-2175,2177,2178</b>	<b>32-44-44</b>	<b>AP-2146</b>
<b>MABS</b>	<b>MLGW</b>	<b>AHA2261</b>	<b>32-44-86</b>	<b>AP-2169</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA2424</b>	<b>32-45-83</b>	<b>AP-2191</b>
<b>MABS</b>	<b>BRAKE</b>	<b>AHA2331,32,34,35</b>	<b>32-45-14</b>	<b>AP-2184</b>
<b>MABS- LORAL</b>	<b>BRAKE</b>	<b>90005025-3</b>	<b>32-44-90</b>	<b>AP-912</b>
<b>ABSC</b>	<b>BRAKE</b>	<b>99-8003-5 (9544397)</b>	<b>98-35161C</b>	<b>N/A</b>
<b>ALS</b>	<b>BRAKE</b>	<b>99-8003-25 (9536788)</b>	<b>PQ2386CE</b>	<b>N/A</b>



<b>ALS</b>	<b>MLGW</b>	<b>154251-1</b>	<b>32-40-05</b>	<b>12-463</b>
<b>ALS</b>	<b>BRAKE</b>	<b>154252-2</b>	<b>32-40-06</b>	<b>12-466</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2601042-4 / 2601042-5</b>	<b>32-40-03</b>	<b>12-501</b>
<b>ALS</b>	<b>NLGW</b>	<b>2601045-2</b>	<b>32-40-02</b>	<b>12-562</b>
<b>ALS</b>	<b>MLGW</b>	<b>2601181-1</b>	<b>32-40-01</b>	<b>12-499</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2601182-5/-6</b>	<b>32-40-02</b>	<b>12-494</b>
<b>ALS</b>	<b>MLGW</b>	<b>2601411-1/-2</b>	<b>32-40-07</b>	<b>12-509</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2601412-1/-2</b>	<b>32-40-08</b>	<b>12-508</b>
<b>AIS</b>	<b>MLGW</b>	<b>2601571-1</b>	<b>32-40-01</b>	<b>12-505</b>
<b>ALS</b>	<b>MLGW</b>	<b>2601901-1/-2/-4/-5/-6/-7</b>	<b>32-45-10</b>	<b>12-515</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2601902-1/-2/-3/-4/-5/-6/-30/-40/-</b>	<b>32-41-30</b>	<b>12-516</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2602012-30/-40/-50</b>	<b>32-41-30</b>	<b>12-516</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2601902-3/-4/-6/-30/-40/-60</b>	<b>32-41-30</b>	<b>12-516</b>
<b>ALS</b>	<b>MLGW</b>	<b>2603561-3/4/5/7/9/10/11/12/13/</b>	<b>32-45-01</b>	<b>12-524</b>
<b>ALS</b>	<b>MLGW</b>	<b>2604561-1</b>	<b>32-40-03</b>	<b>12-539</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2605662-1/-2/-3/-20</b>	<b>32-45-17</b>	<b>12-582</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2605155-1/-2</b>	<b>32-45-17</b>	<b>12-582</b>
<b>ALS</b>	<b>MLGW</b>	<b>2606671-1/-2/-3</b>	<b>32-40-09</b>	<b>12-558</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2606672-1/-2/-3/-4</b>	<b>32-40-08</b>	<b>12-557</b>
<b>ALS</b>	<b>NLGW</b>	<b>2606735-1/-2</b>	<b>32-43-01</b>	<b>12-562</b>
<b>ALS</b>	<b>MLGW</b>	<b>2606741-1</b>	<b>32-43-02</b>	<b>12-563</b>
<b>ALS</b>	<b>MLGW</b>	<b>2606801-1/-2/-3/-4</b>	<b>32-42-06</b>	<b>12-578</b>
<b>ALS</b>	<b>AXEL SLEEVES</b>	<b>2606573 / 2607293 / 2607513 &amp; 2608191</b>	<b>32-42-06</b>	<b>12-578</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2606802</b>	<b>32-42-02</b>	<b>12-560</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2606822-1</b>	<b>32-42-03</b>	<b>12-571</b>
<b>ALS</b>	<b>MLGW</b>	<b>2607081-1/-2/-3</b>	<b>32-45-12</b>	<b>12-569</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2607092-1/-2/-3/-4</b>	<b>32-43-03</b>	<b>12-564</b>
<b>ALS</b>	<b>NLGW</b>	<b>2607825-1/-2</b>	<b>32-40-10</b>	<b>12-579</b>
<b>ALS</b>	<b>MLGW</b>	<b>2608811-3/-5</b>	<b>32-43-04</b>	<b>12-585</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2608812-6/-7/-10/-11</b>	<b>32-43-13</b>	<b>12-629</b>

<b>ALS</b>	<b>MLGW</b>	<b>260889I-1/-1A/-1B/-1C</b>	<b>32-44-01</b>	<b>12-583</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2608892-1</b>	<b>32-44-02</b>	<b>12-584</b>
<b>Page 5 of 10</b>				
<b>AVIATION BRAKE SERVICE</b>				
<b>MANUAL CONTROL</b>				
<b>MAKER</b>	<b>DESCRIPTION</b>	<b>P/N</b>	<b>MANUAL</b>	<b>MFG CODE</b>
<b>ALS</b>	<b>MLGW</b>	<b>2609471-2/-3</b>	<b>32-44-05</b>	<b>12-589</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2609472-4</b>	<b>32-44-08</b>	<b>12-607</b>
<b>ALS</b>	<b>MLGW</b>	<b>2609801-1</b>	<b>32-40-11</b>	<b>12-591</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2610132-3/-4/-5/-6</b>	<b>32-42-27</b>	<b>12-602</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2610182-3/-4/-5/-6</b>	<b>32-42-27</b>	<b>12-602</b>
<b>ALS</b>	<b>MLGW</b>	<b>2610181-2/-3/-4/-5/-6</b>	<b>32-41-11</b>	<b>12-601</b>
<b>ALS</b>	<b>MLGW</b>	<b>2611201-1</b>	<b>32-47-01</b>	<b>12-604</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2611202-2, -2A, -2B</b>	<b>32-47-04</b>	<b>D2007110000038</b>
<b>ALS</b>	<b>MLGW</b>	<b>2611811-1</b>	<b>32-47-05</b>	<b>12-608</b>
<b>ALS</b>	<b>NLGW</b>	<b>2611205-2</b>	<b>32-47-06</b>	<b>12-611</b>
<b>ALS</b>	<b>MLGW</b>	<b>2612201-2/-3</b>	<b>32-41-12</b>	<b>12-609</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2612152-1;2;3;4/2612202-1;2;3;</b>	<b>32-42-28</b>	<b>12-610</b>
<b>ALS</b>	<b>MLGW</b>	<b>2612301-2</b>	<b>32-40-12</b>	<b>12-615</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2612302-1</b>	<b>32-40-13</b>	<b>12-614</b>
<b>ALS</b>	<b>MLGW</b>	<b>2612311-1</b>	<b>32-40-14</b>	<b>12-617</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2612312-1</b>	<b>32-40-15</b>	<b>12-618</b>
<b>ALS</b>	<b>BRAKE</b>	<b>2612412-1 / 2612412-1A</b>	<b>32-43-12</b>	<b>12-626</b>
<b>ALS</b>	<b>MLGW</b>	<b>2615001-1</b>	<b>32-40-16</b>	<b>12-699</b>
<b>BFG</b>	<b>W &amp; B</b>	<b>STANDARD</b>	<b>32-49-01</b>	<b>12-688</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1190</b>	<b>32-40-16</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1203-X</b>	<b>32-46-78</b>	<b>N/A</b>

<b>BFG</b>	<b>BRAKE</b>	<b>2-1287-1</b>	<b>573</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1329-2/-3</b>	<b>32-46-73</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1367-X / 2-1195-X/2607092-1/</b>	<b>32-43-03</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1444</b>	<b>32-40-20</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1449</b>	<b>32-44-37</b>	<b>N/A</b>	
<b>BFG</b>	<b>STEEL HEAT SINK</b>	<b>304-330</b>	<b>32-40-62</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1457-7</b>	<b>32-40-26</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1465</b>	<b>32-46-71</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1466-3/-4/-5</b>	<b>32-42-17</b>	<b>N/A</b>	
<b>BFG</b>	<b>STEEL HEAT SINK</b>	<b>304-332</b>	<b>32-40-61</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1474-X</b>	<b>32-40-30</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1502-X</b>	<b>32-46-41</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1504</b>	<b>32-46-61</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1509</b>	<b>32-46-62</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1515-1/2-1515-2</b>	<b>32-46-02</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1517/-1</b>	<b>32-46-70</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1521-X</b>	<b>32-46-03</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1522-1</b>	<b>32-46-72</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1526-X</b>	<b>32-44-38</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1528-X</b>	<b>32-46-42</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1529-X</b>	<b>32-46-43</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1530-2</b>	<b>32-46-44</b>	<b>N/A</b>	
<b>Page 6 of 10</b>					
<b>AVIATION BRAKE SERVICE</b>					
<b>MANUAL CONTROL</b>					
	<b>MAKER</b>	<b>DESCRIPTION</b>	<b>P/N</b>	<b>MANUAL</b>	<b>MFG CODE</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1542-SERIES</b>	<b>32-41-79</b>	<b>N/A</b>	
<b>BFG</b>	<b>BRAKE</b>	<b>2-1549-3</b>	<b>32-46-86</b>	<b>N/A</b>	

<b>BFG</b>	<b>BRAKE</b>	<b>2-1559-SERIES</b>	<b>32-46-46</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1565</b>	<b>32-46-88</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1566</b>	<b>32-40-43</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1572</b>	<b>32-41-63</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1574</b>	<b>32-46-26</b>	<b>N/A</b>
<b>BFG-BEECH</b>	<b>BRAKE</b>	<b>2-1576 - 101-380096-1</b>	<b>32-46-27</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1577-SERIES</b>	<b>32-41-81</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1578-SERIES</b>	<b>32-41-82</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1579-2</b>	<b>32-48-71</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1582; OPTX</b>	<b>32-49-01</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1586</b>	<b>32-40-47</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1587-X</b>	<b>32-40-48</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1599</b>	<b>32-48-31</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1600, -1,-2-3</b>	<b>32-41-79</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1605-1/-2</b>	<b>32-48-33</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1624,2-1624 OPT2</b>	<b>32-49-03</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1684</b>	<b>32-41-87</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1707-1/-2</b>	<b>32-49-12</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1699-SERIES</b>	<b>32-49-10</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1700</b>	<b>32-48-10</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1711</b>	<b>32-44-01</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-1728</b>	<b>32-41-88</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-699</b>	<b>32-5-6</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-784-1</b>	<b>32-5-6</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-872</b>	<b>32-40-4</b>	<b>N/A</b>
<b>BFG</b>	<b>BRAKE</b>	<b>2-873</b>	<b>32-40-03</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1069</b>	<b>32-40-2</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGVV</b>	<b>3-1070 &amp; 3-1395</b>	<b>32-40-01</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1081</b>	<b>32-40-5</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1104</b>	<b>32-40-10</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW'</b>	<b>3-1215</b>	<b>32-40-5</b>	<b>N/A</b>

<b>BFG</b>	<b>NLGW</b>	<b>3-1251</b>	<b>32-5-7</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1287</b>	<b>32-40-15</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1306-XSERIES3-1414</b>	<b>32-40-21</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1311</b>	<b>32-41-03</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGVV'</b>	<b>3-1319-SERIES</b>	<b>32-42-01</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1341-1</b>	<b>32-45-23</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1349</b>	<b>32-42-02</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1354</b>	<b>32-40-11</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1357; -1</b>	<b>32-45-24</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1365</b>	<b>32-41-03</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW'</b>	<b>3-1368</b>	<b>32-40-16</b>	<b>N/A</b>
	<b>MLGW</b>	<b>3-1375</b>	<b>32-41-03</b>	<b>N/A</b>
<b>Page 7 of 10</b>				
<b>AVIATION BRAKE SERVICE</b>				
<b>MANUAL CONTROL</b>				
<b>MAKER</b>	<b>DESCRIPTION</b>	<b>P/N</b>	<b>MANUAL</b>	<b>MFG CODE</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1398-SERIES</b>	<b>32-40-19</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1399-SERIES</b>	<b>32-45-42</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1409</b>	<b>32-41-17</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1418,OPT1 TO OPT4</b>	<b>32-47-42</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1422/1427/1428</b>	<b>32-40-22</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1423-SERIES</b>	<b>32-40-24</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1426</b>	<b>32-47-28</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1435-SERIES</b>	<b>32-40-12</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1436</b>	<b>32-45-69</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1438-SERIES</b>	<b>32-40-32</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1439-5/-6</b>	<b>32-40-31</b>	<b>N/A</b>

<b>BFG</b>	<b>NLGW</b>	<b>3-1442</b>	<b>32-40-17</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1448</b>	<b>32-41-17</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1460</b>	<b>32-47-61</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1470-SERIES</b>	<b>32-41-12</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1471-SERIES</b>	<b>32-45-01</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1479-SERIES</b>	<b>32-45-02</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1480-SERIES</b>	<b>32-45-68</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1481</b>	<b>32-47-26</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1484</b>	<b>32-45-03</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1485</b>	<b>32-45-70</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1490-1</b>	<b>32-45-43</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1510/-1</b>	<b>32-41-51</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1491-SERIES</b>	<b>32-41-18</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1518-SERIES</b>	<b>32-45-77</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1527-SERIES</b>	<b>32-45-45</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1528</b>	<b>32-47-71</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1530-SERIES</b>	<b>32-41-20</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1531-SERIES</b>	<b>32-41-13</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1546</b>	<b>32-41-75</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1545-1</b>	<b>32-48-72</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1547</b>	<b>32-41-74</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1550-SERIES</b>	<b>32-49-02</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1551</b>	<b>32-49-04</b>	<b>N/A</b>
<b>BFG</b>	<b>MLG W</b>	<b>3-1557</b>	<b>32-40-49</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1558</b>	<b>32-40-50</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1574</b>	<b>32-48-35</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1573-1</b>	<b>32-48-32</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1559</b>	<b>32-40-51</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1590</b>	<b>32-49-05</b>	<b>N/A</b>
<b>BFG</b>	<b>MLGW</b>	<b>3-1609-1</b>	<b>32-48-28</b>	<b>N/A</b>
<b>BFG</b>	<b>NLGW</b>	<b>3-1610-1</b>	<b>32-48-29</b>	<b>N/A</b>



<b>MESSIER</b>	<b>BRAKE</b>	<b>286349; -0-0; -0-6; -0-8; -0-9; -0-1</b>	<b>32-42-27</b>	<b>F6137</b>
<b>MESSIER</b>	<b>NLGW</b>	<b>286351005-SERIES</b>	<b>32-41-12</b>	<b>F6137</b>
<b>MESSIER</b>	<b>NLGW</b>	<b>286351006-SERIES/-7-SERIES</b>	<b>32-41-15</b>	<b>F6137</b>
<b>MESSIER</b>	<b>NLGW</b>	<b>289021012-SERIES</b>	<b>32-41-16</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>289021-SERIES</b>	<b>32-41-23</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>289021122-SERIES</b>	<b>32-41-18</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>ALL</b>	<b>32-41-24</b>	<b>F6137</b>
<b>MESSIER</b>	<b>STANDAR REP</b>	<b>ALL MODELS</b>	<b>32-09-01</b>	<b>F6137</b>
<b>MESSIER</b>	<b>STEEL BRAKE</b>	<b>C20060-100; -1001; -1002; -100</b>	<b>32-44-24</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C2014000; -1; -2; -C2014001; -1</b>	<b>32-46-22</b>	<b>F6137</b>
<b>MESSIER</b>	<b>BRAKE</b>	<b>C20194500; -1; -2; -3; -4; C20194</b>	<b>32-46-37</b>	<b>F6137</b>
<b>MESSIER</b>	<b>CARBON BRAKE</b>	<b>C20194500;-1; -2; -3; -4; -5; -6;-7;</b>	<b>32-46-66</b>	<b>F6137</b>
<b>MESSIER</b>	<b>MLGW</b>	<b>C20195150-X/C20195151-SERIE</b>	<b>32-46-38</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C20626200 S277A016-551</b>	<b>32-49-83</b>	<b>F6137</b>
<b>Page 9 of 10</b>				
<b>AVIATION BRAKE SERVICE</b>				
<b>MANUAL CONTROL</b>				
<b>MAKER</b>	<b>DESCRIPTION</b>	<b><u>P/N</u></b>	<b>MANUAL</b>	<b>MFG CODE</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C20194601/02/03/0-1/05/06/07/</b>	<b>32-46-69</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C20195002/C20195152</b>	<b>32-47-19</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C20195162</b>	<b>32-47-46</b>	<b>F6137</b>
<b>MESSIER</b>	<b>BRAKE</b>	<b>C20210000-XSERIES/ 0200-SER</b>	<b>32-44-51</b>	<b>F6137</b>
<b>MESSIER</b>	<b>BRAKE</b>	<b>C202106 Series</b>	<b>32-44-69</b>	<b>F6137</b>
<b>MESSIER</b>	<b>BRAKE</b>	<b>C20210500-SERIES</b>	<b>32-44-68</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C20211000-SERIES/C20211001-</b>	<b>32-41-26</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C20211100-SERIES/C20211101</b>	<b>32-44-53</b>	<b>F6137</b>
<b>MESSIER</b>	<b>WHEEL</b>	<b>C20211150/51/60/61</b>	<b>32-44-54</b>	<b>F6137</b>























**AIRCRAFT**

**SABIENIER 75**

**SN601**

**FALCON 20**

**F0 28**

**SAAB340**

**DORNIER DO228**

**YVESTYVIND 1125 G150**

**G150**

**IAI1125**

**S-76B**

**FOK 50**

**Fo 70/100**

**CL600**

**CL600**

**BEECH 400A**

**GULFSTREAM IIB,III AND IV**

**CRJ 100/200**

**GULSTREAM IV**

**CRJ100/200**

**FOKKER 70/100**

**FOKKER F0100/F070**

**ATR42/500**

**G200**

**CRJ700, CRJ705, CRJ900 & CRJ950**

**CRJ700**



<b>DC9-40/50</b>
<b>DC9-30</b>
<b>EMB-190</b>
<b>F-28</b>
<b>DC10-10</b>
<b>MD81.82&amp;87</b>
<b>GIIB ,111,1V</b>
<b>DC10-10</b>
<b>DC10-30/40</b>
<b>DC10-30/40</b>
<b>FOK 70/100</b>
<b>DC10-30/40 MD 11</b>
<b>CESSNA 500&amp;550</b>
<b>IAI-201/101, DIIC 6</b>
<b>SABERLINER 75</b>
<b>BEECH-200</b>
<b>BEECH200</b>
<b>WESTWIND 1124</b>
<b>LEARJET25.35,55,60</b>
<b>LEARJET25.35,55,60</b>
<b>FALCON 50</b>
<b>FALCON 50</b>
<b>SIKORSKY UII60A</b>
<b>F-28</b>
<b>(MU-300)</b>
<b>MD81-82-87</b>
<b>MD87</b>
<b>GULFSTREAM 11B,IH,TV</b>
<b>GULFSTREAM IIB,III</b>
<b>CESSNA 550</b>
<b>CESSNA 550</b>



<b>CL600&amp;CL601/G 200</b>
<b>Do228-212</b>
<b>DO-228-212</b>
<b>SAAB 340</b>
<b>CL604, CRJ100, CR3200, G200</b>
<b>CRJ-100/200</b>
<b>G IIB,III,IV</b>
<b>METRO 23</b>
<b>LEARJET 60</b>
<b>F-100/F-70</b>
<b>CL60</b>
<b>CL60</b>
<b>SAAB 340, GROB180</b>
<b>G200</b>
<b>ATR-72</b>
<b>ATR-72</b>
<b>CRJ705/900/950</b>
<b>FALCON 900EX-EASy AIRCRAFT</b>
<b>EMB-170/190/195, ARJ21</b>
<b>EMB 170 175</b>
<b>EMB 170 175</b>
<b>EMB 170/190</b>
<b>DORNIER 328-100</b>
<b>DORNIER 328-100</b>
<b>DORNIER 328-100</b>
<b>EMB-190/195</b>
<b>EMB-190/195</b>
<b>PIIENON 100</b>
<b>CONVA1R 240/340/440/540/580/600/640</b>
<b>CONVA1R 340/440/540/580/600/640</b>
<b>FH227-F28, CA212-300</b>



<b>ALL</b>
<b>ALL</b>
<b>ALL</b>
<b>BEECH 1900</b>
<b>L-100</b>
<b>C-130</b>
<b>C-130</b>
<b>C-130</b>
<b>C-130</b>
<b>C-130</b>
<b>C-130</b>
<b>C-130</b>
<b>C-130</b>
<b>C-130</b>
<b>BRAKES AND WHEELS</b>
<b>GIV</b>
<b>FOKKER 27</b>
<b>JETSTREAM 31</b>
<b>JETSTREAM 31</b>
<b>JETSTREAM 31</b>
<b>CASA100/200</b>
<b>FOKKER 27</b>
<b>JETSTREAM 31/32</b>
<b>JETSTREAM 31/32/41</b>
<b>CN235</b>
<b>SD330/360</b>
<b>SD 330,360</b>
<b>SD360</b>
<b>B737</b>
<b>CASA CN235</b>
<b>CN235</b>





<b>DC8F-61/62</b>
<b>DC-8-61/62</b>
<b>737-100/200</b>
<b>737-100/200</b>
<b>B727</b>
<b>B-727-100/200</b>
<b>DC8-63</b>
<b>DC-8-63,DC-8-62H</b>
<b>B-737-100/200</b>
<b>747-100</b>
<b>747-100</b>
<b>747-100</b>
<b>747-200</b>
<b>B-747-200</b>
<b>B-727</b>
<b>747-200/300</b>
<b>747-200/300</b>
<b>737-200/300/400/500</b>
<b>737-200/300/400/500</b>
<b>767</b>
<b>767</b>
<b>A-300 AND A300-600</b>
<b>A-300 AND A300-600</b>
<b>A300</b>
<b>A310</b>
<b>747</b>
<b>767</b>
<b>737-300/400/500/600/700/800/900/BBJ</b>
<b>767-300</b>
<b>767-300</b>

<b>MD-80</b>
<b>MD-80</b>
<b>AIRCRAFT</b>
<b>MD-11</b>
<b>MD-11</b>
<b>737-400 HGW</b>
<b>A-330/A-340</b>
<b>A330/A340</b>
<b>A330/A340</b>
<b>777</b>
<b>777</b>
<b>777</b>
<b>777</b>
<b>A330-340</b>
<b>A330/340</b>
<b>737-600/700</b>
<b>737-600/700</b>
<b>737-600/700/800/900/BBJ</b>
<b>737-600/700/800/900/BBJ</b>
<b>767-300</b>
<b>B-737-900ER</b>
<b>STANDARD PRACTICES MANUAL</b>
<b>B727-100/200</b>
<b>226TC/METRO II,III,IV/ MERLIN III, IV</b>



<b>CJ.CJI, CITATION JET 525</b>
<b>DHC8-100</b>
<b>B767-400ER, 777-200, 777-200ER, 777-300</b>
<b>A320</b>
<b>BEECHCRAFT</b>
<b>BEECH200,300,350 C-12A.C-12C</b>
<b>A330/340</b>
<b>A330/A340</b>
<b>L45</b>
<b>EMB- ERJ145ER; ERJ135</b>
<b>B737-600/700</b>
<b>737-900/737NG/BBJ</b>
<b>DASH 8-202</b>
<b>A320</b>
<b>O-400/DASH 8</b>
<b>EMBRAER ERJ145LR</b>
<b>A318-319-320</b>
<b>EMBRAER / ERJ145LR</b>
<b>EMBRAER ERJ</b>
<b>SUPER TUCANO</b>
<b>SUPERJET 100</b>
<b>A320</b>
<b>LAC188 (EFL188</b>
<b>707</b>
<b>727-100</b>
<b>727</b>
<b>727-100</b>
<b>727-200</b>
<b>727-100</b>
<b>707</b>
<b>727-100</b>



<b>DASH-8</b>
<b>DHC-8-300</b>
<b>PJAGGIO P-180</b>
<b>A320</b>
<b>757-200C</b>
<b>747-400</b>
<b>DASH 8-300</b>
<b>BEENCHCRAFT</b>
<b>737-400</b>
<b>JETSTREAM J-3LJ-32</b>
<b>CESSNA CITATION M500,550,551,S60</b>
<b>A330/A340</b>
<b>A320</b>
<b>ATR42 300/400/500</b>
<b>CJ, CJ-1,525</b>
<b>ATR-42</b>
<b>A320 <sup>A</sup></b>
<b>A319- A320-A321,A318</b>
<b>A330/340</b>
<b>LEARJET MOD 45</b>
<b>A330/340</b>
<b>737-600/700-800</b>
<b>EMBRAER145</b>
<b>737-600/737-700,737NG</b>
<b>737-600-700-800</b>
<b>0-400/B OM B ARD1ER</b>
<b>0-400/B OMBARDIER</b>
<b>737</b>
<b>EMBRAER ERJ190LR</b>
<b>BOMBARDIER BD-100</b>
<b>BOMBARDIER BD-100</b>

<b>EMBRAER 145</b>
<b>EMBRAER 145</b>
<b>AIRCRAFT</b>
<b>EMBRAER 145</b>
<b>EMBRAEII 145</b>
<b>B-737 NG</b>
<b>B707-300,-400series</b>
<b>ALL</b>
<b>A330/A340</b>
<b>A330</b>
<b>A330/A340</b>
<b>A321</b>
<b>A321-200</b>
<b>A321_</b>
<b>B-747</b>
<b>MD-80/ DC-9</b>
<b>B-747</b>
<b>C-130</b>
<b>C-130</b>
<b>A321</b>
<b>A321</b>
<b>A-310</b>
<b>A300/A300-600/A310</b>



<b>A-300</b>
<b>A-310</b>
<b>A300</b>
<b>A-310</b>
<b>A-300</b>
<b>A-310</b>
<b>A-310</b>
<b>ALLA-300 -X SERIES</b>
<b>A300</b>
<b>A300</b>
<b>A-300</b>
<b>A-300</b>
<b>A-300</b>
<b>B-737</b>
<b>AIRCRAFT</b>
<b>A-330-JV</b>
<b>A-310</b>
<b>A-318/A319/A320</b>
<b>A-310</b>
<b>A-300</b>
<b>A-310</b>
<b>A-310</b>
<b>A-310</b>
<b>A-300/A-310</b>



















